

# SDK

This section includes the following topics:

- [How to plug-in the SDK using the CLI Utilities](#)
- [How to plug-out the SDK using the CLI Utilities](#)

## How to plug-in the SDK using the CLI Utilities

This section describes how to plug-in the SDK using the CLI Utilities.

### Preparation

Before running the command line to plug-in the SDK, you should copy all the relevant SDK files to the distribution folder under the *<precise\_root>* of the server with the Precise FocalPoint. Typically the files will be *<SDK\_name>.xml* and *<SDK\_name>.zip*.

### Running the Plug-in command

Go to the *<precise\_root>* folder of the server with the Precise FocalPoint and run the following command:

<b>Windows</b>	<code>infra\bin\psin_cli.bat</code> <code>-action in-sdk-plug-in</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter installation-package=&lt;SDK_name&gt;.xml</code>
<b>UNIX</b>	<code>./infra/bin/psin_cli.sh</code> <code>-action in-sdk-plug-in</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter installation-package=&lt;SDK_name&gt;.xml</code>

## How to plug-out the SDK using the CLI Utilities

This section describes how to plug-out the SDK using the CLI Utilities.

### Preparation

Before using the plug-out command, verify that you don't have a running SDK instance of the technology that you are about to plug-out.

### Running the Plug-out command

Go to the *<precise\_root>* folder of the server with the Precise FocalPoint and run the following command:

<b>Windows</b>	<code>infra\bin\psin_cli.bat</code> <code>-action in-sdk-plug-out</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter sdk-technology-code=&lt;SDK_technology_code&gt;.xml</code>
<b>UNIX</b>	<code>./infra/bin/psin_cli.sh</code> <code>-action in-sdk-plug-out</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter sdk-technology-code=&lt;SDK_technology_code&gt;.xml</code>