

SDK

This section includes the following topics:

- [How to plug-in the SDK using the CLI Utilities](#)
- [How to plug-out the SDK using the CLI Utilities](#)

How to plug-in the SDK using the CLI Utilities

This section describes how to plug-in the SDK using the CLI Utilities.

Preparation

Before running the command line to plug-in the SDK, you should copy all the relevant SDK files to the distribution folder under the *<precise_root>* of the server with the Precise FocalPoint. Typically the files will be *<SDK_name>.xml* and *<SDK_name>.zip*.

Running the Plug-in command

Go to the *<precise_root>* folder of the server with the Precise FocalPoint and run the following command:

Windows	<code>infra\bin\psin_cli.bat</code> <code>-action in-sdk-plug-in</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter installation-package=<SDK_name>.xml</code>
UNIX	<code>./infra/bin/psin_cli.sh</code> <code>-action in-sdk-plug-in</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter installation-package=<SDK_name>.xml</code>

How to plug-out the SDK using the CLI Utilities

This section describes how to plug-out the SDK using the CLI Utilities.

Preparation

Before using the plug-out command, verify that you don't have a running SDK instance of the technology that you are about to plug-out.

Running the Plug-out command

Go to the *<precise_root>* folder of the server with the Precise FocalPoint and run the following command:

Windows	<code>infra\bin\psin_cli.bat</code> <code>-action in-sdk-plug-out</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter sdk-technology-code=<SDK_technology_code>.xml</code>
UNIX	<code>./infra/bin/psin_cli.sh</code> <code>-action in-sdk-plug-out</code> <code>-i3-user admin</code> <code>-i3-clear-password admin</code> <code>-parameter sdk-technology-code=<SDK_technology_code>.xml</code>